


Figure 1



**Pigments Photoinitiators** 100% Solids Liquid Coating Monomers Oligomers

Figure 2, Prepare Opaque Corrosion Resistant UV cured coatings



Application to Bottom by

HVLP or Electrostatic
Spray 21 Application to Top by HVLP or Electrostatic Spray 19 Underhood Auto Part 20 Figure 3, Applying Coating Rotating tooling to hold part 24 Rotating Fixture 22 -Application to Side by HVLP or Electrostatic Spray 25

Conveyor — Chain on Edge or Overhead 23



Figure 4, Cure Coating

